
TVM-N – Assembly Instruction

1. Unpack the test stand
2. Plug in the power supply



3. Attach a force gauge with an internal sensor



TVM-N – Assembly Instruction

4. Attach a force gauge with an internal sensor
 - a. Dismount the red marked object



By unscrewing the four screws



TVM-N – Assembly Instruction

- b. Connect the FH force gauge with the test stand (only FH U 5.1 series)



5. Alternative, if an external sensor is to be mounted:

- a. Take the black angle piece



TVM-N – Assembly Instruction

- b. Attach the black angle piece to the upper part of the test stand



- c. Attach the external sensor

TVM-N – Assembly Instruction

- d. Connect the sensor with the display unit (please see the operation manual)



Ready for measuring!